# 10,083,724.

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,727,428 B2

Page 1 of 1

DATED INVENTOR(S) : Archer et al.

: April 27, 2004

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Column 5,

Lines 43-66, delete "...second mounting axis generally parallel to said first side wall; said first and second mounting axes being substantially equidistant..." and insert -- ...communication fixture along a second mounting axis generally parallel to said first side wall; said supporting structure further comprises an upper leg spaced apart from a lower leg, said upper and lower legs connecting said first side wall to a joining strut extending between distal ends of said upper and lower legs; said first and second mounting axes being substantially equidistant... --.

#### Column 3,

Lines 54 and 60, delete "...in convention fashion..." and insert -- in conventional fashion... --.

### Column 6.

Line 2, delete "...flanges an an exterior..." and insert -- flanges on an exterior --. Line 31, delete "...first and third mounting axis..." and insert -- first and third mounting axes --.

Signed and Sealed this

Thirtieth Day of November, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office